

**Bethal Pump Station 2
Mpumalanga, South Africa
October 2004**

The pump station well was congested with solid sewerage and the pump burnt out.



A. Raw sewerage running out of the pump station



E. Congested pump well that caused the problem. Dosing was implemented



B. The congested well and flow to pump



F. 3 Days after dosing commenced



C. Raw sewerage flowing to the river



G. 7 Days after dosing commenced



D. Dosing the product to biodegrade the effluent flowing to the river



H. 10 Days after dosing commenced